1-ENGINEER 1-FILE

orm Approved. Budget Bureau No. 42-R1424

UNITED STATES

5. LEASE	1,		÷	•	þ .		;		
LC-060825-	A	.5	1	• :	<u>-</u>	 •	::	-	

DEPARTMENT OF THE INTERIOR	LC-060825-A					
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME MYERS LANGLIE MATTIX UNIT					
(Do not use this form for proposals to drill or to deepen or plug back to a different	MIERS LANGLIE MATTIX UNIT					
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME MYERS LANGLIE MATTIX UNIT					
1. oil gas well other						
	9. WELL NO. 19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
2. NAME OF OPERATOR GETTY OIL COMPANY						
	10. FIELD OR WILDCAT NAME					
3. ADDRESS OF OPERATOR P. O. BOX 730, HOBBS, NEW MEXICO 88240						
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA					
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	SEC. 30-T-23-S, R-37-E-37-					
below.) AT SURFACE: 1980' FNL & 660' FEL, SEC. 30	12. COUNTY OR PARISH 13. STATE					
AT TOP PROD. INTERVAL:	LEA NEW MEXICO					
AT TOTAL DEPTH:	14. API NO. 3-5-1-5 B 3-3-3-2					
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 1974 P. 2525					
REPORT, OR OTHER DATA	15 CLEVATIONS (SUCH SET 1997)					
KEI OKI, OK OTHEK DAIM	15. ELEVATIONS (SHOW DECKUB, AND WD)					
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3333 D.I.					
TEST WATER SHUT-OFF	ခေါ်လူရှိ ရွာ မိမွှဲသွဲမွာ					
FRACTURE TREAT	원물병용 - 판 원범생물					
SHOOT OR ACIDIZE						
REPAIR WELL	(NOTE: Report results of multiple completion or zone					
PULL OR ALTER CASING []	change on Form 9-330.)					
MULTIPLE COMPLETE						
ABANDON*	(CORRECTION)					
(other) DEEPEN 60'						
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and						
measured and true vertical depths for all markers and zones pertinen	it to this work.)*					
Ran 6-1/8" bit and cleaned out to original TD at						
3696', new TD. Ran 7" X 2-7/8" Baker Model "R"						
packer set at 3335'. Western Company treated or						
15% NE Acid. Pulled packer and 2-7/8" tubing. Set 2-3/8" 4.7# J-55 tubing at						
2693'. Ran rods and put well on pump 4-30-77.	그 그 그는 그는 일 화석 전에 가 무리 전복 설렜다.					
	무슨 사람들이 얼마 얼마를 걸릴 때 그리고 살아 살아 먹었다.					
THIS NOTICE TO CORRECT NEW TD. CHANGED FROM 363	39' to 3696'. 🖓 🔞 🔞 😘 🗒					
	그 그 그 그 그 그 물 옷을 되면 그 속이 화를 손을 다니다.					
	医二甲基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲基基甲					
	그 그 그 그 사람들이 살아 가장 하는 것이 없다.					
Subsurface Safety Valve: Manu. and Type	Set @*Ft.					
18. I hereby certify that the foregoing is true and correct	기계 기					
SIGNED SIGNED SIGNED TITLE AREA SUPERINTE	ENDENT 2-16-78					
SIGNED Dala P Crockett	DATE					

(This space for Federal or State office use)

APPROVED BY ... CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

FEB 21 1978

Ü. **S.** ĞEOLOGICAL SURVEY HOBBS, NEW MEXICO