## UNITED STATES SUBMIT IN TRIPLICATE\* (Other instructions on reverse side) 5.

Budget Bureau No. 42-R1424.

GEOLOG' SURVEY			LC060825A		
SUNDRY NOTICES AND RE  (Do not use this form for proposals to drill or to decuse "APPLICATION FOR PERMIT	PORTS O	N WELLS covers to a different reservoir.	). IF INDIAN, ALLOTTEE		
Use "APPLICATION FOR PERMIT.  1.	— for such proj	posais.)	7. UNIT AGREEMENT NA	M E	
OIL GAS WELL OTHER			Myers Langlie- 8. FARM OR LEASE NAM	Mattix_Unit	
2. NAME OF OPERATOR					
Getty Oil Company 3. ADDRESS OF OPERATOR		1077	Myers Langlie- 9. WELL NO.	Mattix Unit	
P. O. Box 1351, Midland, Texas 797	702 ance with any S	tate requirements.*	10. FIELD AND POOL, O	4 R WILDCAT	
See also space 17 below.) At surface		The sear County and	Langlie- 11. SEC., T., R., M., OR E SURVEY OR AREA	Mattix	
Unit Letter F, 1650' FNL & 1980' FWL, Sec. 30-23S-37E				Sec. 30-23S-37E	
14. PERMIT NO. 15. ELEVATIONS (S.	how whether DF, I	RT, GR, etc.)	12. COUNTY OR PARISH	1	
3352'	DF		Lea	New Mexico	
16. Check Appropriate Box To	o Indicate No	ature of Notice, Report, o	Other Data		
NOTICE OF INTENTION TO:	1	SUBS	EQUENT REPORT OF:		
TEST WATER SHUT-OFF PULL OR ALTER CASI	NG	WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TREAT MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING C	11	
SHOOT OR ACIDIZE ABANDON*		SHOOTING OR ACIDIZING	ABANDONME	X X	
REPAIR WELL CHANGE PLANS (Other)		(Other)Casing (	Connections  old of multiple completion mpletion Report and Log fo	on Well	
proposed work. If well is directionally drilled, give s nent to this work.)*  Riser on 8-5/8" OD and 5-1/2" OD of Inspected by L. A. Clements on Man	casing bro	ought to surface.			
18. I he ( ) Creek that the foregoing is true and correct SIGNED . R. Crow	TITLE	Lead Clerk	DATE Marc	h 17, 1977	
(This space for Federal or State office use)					
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		ACCEPTED FO	R RECORD	

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO