


(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	1
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

S. S. Blinbury (b, 307-1) Midland, Texas, October 25, 1951

Well No. 5 is located 500 ft. from N line and 1380 ft. from E line of sec. 31

SE/4 SW/4 Sec. 31 23-S 37-E N 10° E  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Langlie-Mattix Lea New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3315 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 3453 - Dolomite

Ran and cemented 3443' 7" casing set at 3453' with 545 sacks cement. Completed 12:30 AM 10-15-51.

Tested casing with 1000# pressure 1 hour okay 10-17-51. Commenced drilling cement plug at 12:30 AM 10-18-51. Drilled plug and 1' formation. Tested casing with 1000# pressure 1 1/2 hours. Tested okay. Drilling proceeded.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas CompanyAddress Box 1270Midland, TexasBy H. J. VanTitle List. Supt.