

DUPLICATE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 03254516Unit 4152

OCT 21 1951

CONSERVATION COMMISSION
HOBBS-OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

E. E. Blinebry (b) NCT-1 _____ October 19 _____, 1951

Well No. 5 is located 660 ft. from N line and 1280 ft. from E line of sec. 3135/4 35/4 Sec. 31 23-S 37-A 10TH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Lanzlie-Lattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3315 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

FB: 1195 - Amhy

Ran and cemented 1195' x 5/8" casing set at 1195' with 700 sacks.
Cement circulated. Completed 7:45 AM 10-5-51.Tested 5/8" casing with 1000 pressure 1 hour 10-7-51. Commenced
drilling cement plug at 9:30 AM 10-7-51. Drig plug and 1' formation.
Tested casing with 1000 pressure for 1 1/2 hours. Tested okay.
Drilling proceeded.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas CompanyAddress Box 1270Midland, TexasBy JHrewTitle Dist. Mgt.

SECRET