

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesUNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease No. <u>032545 (b)</u>
<b>RECEIVED</b>
OCT 10 1951
OIL CONSERVATION COMMISSION FIELD OFFICE

## SUNDRY NOTICES AND REPORTS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

W. W. Hinchey (b) October 5, 1951  
Well No. 5 is located 560 ft. from [N] line and 1160 ft. from [E] line of sec. 31  
23-4 23-4 Sec. 31 23-4 37-8 18-11  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Landlax-Hallix Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5315 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 1195 - Anhy.

Run and cemented 1185' 5/8" casing set at 1185'. Cemented with 700 sacks. Cement circulated. Completed 9:45 PM 10-5-51.

Anticipate drilling cement plug and testing casing by pressure method after 72 hours or at approximately 9:45 AM 10-8-51.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas CompanyAddress Box 1-70Lidland, TexasBy J. A. NewTitle Dist. Supt.