

DUPLICATE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032245 (b)

Unit _____

RECEIVED

SEP 21 1951

OIL CONSERVATION COMMISSION
HOBBS OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

W. W. Glinebry (b) 2-17-4 Midland, Texas September 19, 19 51

Well No. 1 is located 1280 ft. from N line and 2310 ft. from E line of sec. 35

34/4 32/4 23-3 37-3
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Langlie-Lattix Len New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3235 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 3360 - Dolo.

Ran and cemented 3350' 7" casing set at 3360'. Cemented with 4.5 sacks. Completed 5:30 AM 8-12-51.

Rotary rig was released from this well 8-12-51. Cable Tool rig was moved in 7-13-51.

Bailed hole dry and tested casing for 4 hours on 7-13-51. Tested okay. Drilled cement plug and 1' formation on 7-14-51. Tested casing for 4 hours. Tested okay. Drilling proceeded.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By J. H. New

Title Dist. Supt.

