

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 032545(b)
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

E. E. Blinbry (b) NOT-4 Midland, Texas November 21, 1951

Well No. 2 is located 1980 ft. from S line and 1980 ft. from E line of sec. 35
NW/4 SE/4 Sec. 35 23-S 37-E 10N-H
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie-Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3222 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 333 - Red Beds

Ran and cemented 318' 13 3/8" casing set at 327' with 175 sacks cement. Cement circulated. Completed 7:30 AM 11-8-51.

Tested casing 1 hour with 950# pressure on 11-10-51. Commenced drilling cement plug at 8:00 AM 11-10-51. Drilled plug and 1' formation. Tested casing with 950# pressure 1 hour. Tested okay. Drilling proceeded.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Leach Company

Address Box 1270

Midland, Texas

By [Signature]

Title Asst. Dist. Supt.

