NEW MEXICO UIL CONSERVATION COMMISSION

Form C-128

Well Location and/or Gas Progation Plat

Well Location and/or Gas Provation Plat								
	Getty Of	il Co. Owne	is the state of th	Leas			-13-1956	
Operator		r Oil Co.	Operator	Leas	eph Riggs	н В ы		
	_	a .:			~ ~	Pance 27 I	East NMPM	
Well No.	3	Section	1 10	wnsnip_	26 South	_Range_37_1	141111111111111111111111111111111111111	
Located	1980	Feet Fro	m North	Line,	1980	_Feet From_	East Line,	
						91 - Air		
	Lea		_County, Nev	w Mexic	o. G. L. E	levation		
Name of	Producing	Formation_	Queen	Po	ol Langlie-	Mat to gdicate	d Acreage 40	
Name of							and the second of the second o	
	(No	te: All dista	inces must be	from o	uter bounda:	ries of Section	n) rocker	
			İ		1		. ,	
			1					
			!		1	•1		
				•	19		· '	
			1		1980			
	-		+	-+				
			1		1320	660	L _p	
			1					
			1		ì			
	-		+		+			
			1		ļ			
			1		1		•	
NOTE			1					
This secti	on of		1		. 1			
form is to			1		i			
used for g wells only				-+-	-		1	
					!			
			1		ļ			
			İ		i			
					ļ			
V			1		1	_		
		ALE:1"=1000'			701		ahawa mlaa maa	
1. Is the	is Well a D	ual Comp.?	YesNo				above plat was of actual surveys	
2. If th	e angwer t	o Question !	is ves. are t	i '			supervision and	
2. If the answer to Question 1 is yes, are there any other dually completed wells within the					that the same are true and correct to the			
		ge? Ýев		_• ·	best of my k	nowledge and	belief.	
Name					Date Survey	ed 6-13-19	956	
Position.				_	John W West			
Representing					Registered Professional Engineer and/or			
Address				1	Land Survey	or		