



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 65171 (b)  
Unit C.G. Cagle "C"

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

**I - Set of Set Bridge Plug & Complete well.**

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 16, 1957

Well No. 1 is located 990' ft. from N line and 990' ft. from W line of sec. 9

14 / 14 (Sec. and Sec. No.)      26-S (Twp.)      32-E (Range)      (Meridian)

Las Cruces (Field)      Las Cruces (County or Subdivision)      New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3004.1 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled P.S.I. Separation sleeve & set Bridge Plug @ 3220', dumped 1 sack cement.  
Cement from 3212' to 3220'. Checked collars @ 3111', 3154' & 3190' OK.  
Ran Tubing & set @ 2604' with Packer set @ 2593'.  
Completed in Jalnet Pool on 3-13-57.

# ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ames Petroleum Corporation

Address Box 706, Duran, New Mexico

By [Signature]

Title Perm Boss