

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR TEXAS PACIFIC OIL COMPANY, INC		8. FARM OR LEASE NAME FARNSWORTH 4	
3. ADDRESS OF OPERATOR P.O. BOX 4067 MIDLAND, TEXAS 79701		9. WELL NO. 9	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 2310' FWL		10. FIELD AND POOL, OR WILDCAT LANGLIE MATTIX	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA UNIT C, SEC. 4 T-26-S, R-37-E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3002.2' DF		12. COUNTY OR PARISH LEA	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	WELL STATUS X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Shut in. TA'd in March 1965 due to uneconomical production.
Lease is considered to have secondary reserves. Engineering study scheduled but timing is uncertain. There are a number of active Langlie Mattix waterfloods in this area.

DEC 1 1965

18. I hereby certify that the foregoing is true and correct

SIGNED L. Wright TITLE Area Supt DATE 11-7-75

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: