(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

deval Locard 011 Co.

SUNDRY NOTICES AND REPORTS ON WELLS

		-
NOTICE OF INTENTION TO DRILL	 SUBSEQUENT REPORT OF REDRILLING OR REPAIR	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

##/A of 54/4 of Section 12 26-5 37-2 (Meridian) (14 Sec. and Sec. No.) (Twp.) (Range) (Meridian) Filsont			Midland,	Texas, /	mgnet 21	, 19 <u>.43</u>	
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian) (1/4 Sec. and Sec. No.) (Twp.) (Range) (1/4 Sec. and Sec. No.) (Twp.) (Range)				ndft	. from $\left\{egin{array}{c} oldsymbol{E} \ W \end{array} ight\}$ line o	f sec. 13	
Vildest Lee	(½ Sec. and Sec. No.)	(Twp.)		(Merid			
		(County or Subdivision)			(State or Territory)		
(Field) (County or Subdivision) (State of Territory)							

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested 9-5/8" casing with 1000f pumping pressure on August 20, 1943 after allowing comount to set 97 hours. Tested estimatory.

I understand	that this plan of work must receive approval in writing by	the Geological Survey before operations may be commenced.
Company	Memble Cil & Refining Company	
Address	Box 1600, Midland, Texas	
		By Chauce Title Division Superintendent

1944 - 1945 - 1946 - 19

LAR COMMERCIAL CAR NO DECRETATION

•

•

entre de la companya de la companya