

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other Instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Rhodes Gas Storage Unit
2. NAME OF OPERATOR El Paso Natural Gas Co.	8. FARM OR LEASE NAME Cagle "B"
3. ADDRESS OF OPERATOR 1800 Wilco Building	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit M, Sec 15, T-26-S, R-37-E	10. FIELD AND POOL, OR WILDCAT Rhodes Yates-7R
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 15, T-26-W, R-37-E	12. COUNTY OR PARISH Lea
13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input checked="" type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

6/28/79: RUPU and pull tbq.
7/10/79: Finished cleaning out to 3216'.
7/11/79: Ran 5½", 17#, P-110, LT&C liner to 3216'. T/liner @ 2998'.
7/12/79: Perforated liner in Yates-7R 3033' - 3143' (14 holes).
7/13/79: Land production tbq @ 3027'. RDPU.

RECEIVED

SEP 13 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO


18. I hereby certify that the foregoing is true and correct

SIGNED *J. L. Bentley*
(This space for Federal or State office use)

TITLE Production Engineer DATE 9/12/79

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side

OFFICE OF THE
ATTORNEY GENERAL

RECEIVED

SEP 18 1964

O.C.D., HOUSE OFFICE