

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
A. G. Moberly  
Serial Number 030181 b  
Lease or Permit lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT RECORD OF SHOOTING.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		RECORD OF PERFORATING CASING.....	
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING.....	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO ABANDON WELL.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO SHOOT.....		SUPPLEMENTARY WELL HISTORY.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Fort Worth, Texas, January 29, 1938

Following is a notice of intention to do work on land under lease described as follows:

New Mexico Lea County Jal  
(State or Territory) (County or Subdivision) (Field)  
Well No. 1 NE-1/4 Sec. 21 T-26-S, R-37-E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

The well is located 660 ft. S of N line and 660 ft. W of E line of sec. 21  
ground

The elevation of the 2988 above sea level is 2988 ft.

DETAILS OF PLAN OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

FORMATIONS EXPECTED

		Size	CASING (Approx)	
			Set at	Cement
Top of Salt	1150'	13" OD 40#	265' New	250 sacks
Base of Salt	2680'	9-5/8" OD 40#	1125' "	575 "
Top of Brown Lime	2710'	7" OD 24#	2990' "	125 "

First productive gas expected at approximately 3140'

Drilling operations to be commenced immediately.

Approved \_\_\_\_\_  
(Date)

Company THE TEXAS COMPANY

By Tom T. Freeman

Title \_\_\_\_\_  
GEOLOGICAL SURVEY

Title Lands and Leases

West Texas Division

Address \_\_\_\_\_

Address Box 1720, Fort Worth, Texas

NOTE.—Reports on this form to be submitted in triplicate to the Supervisor for approval.

B1 cc New Mexico Oil Conservation Commission, Hobbs, N.M.

1. The first step in the process of identifying a problem is to determine the nature of the problem. This involves a thorough understanding of the situation and the factors that may be contributing to the problem.

[illegible]

100% 0 100 200 300 400 500 600 700 800 900 1000

[illegible]