NUMBER OF COPIE	S RECEIVED		 -
D15	TRIBUTION		
SANTA FE			
FILE			
U.5.G.S.			
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		
PRORATION OFFICE			
OPERATOR		i	- 15

FORM C-103

M1	SCELLA	NEOUS	REP	ORTS ON	WELLS		
(Submit to	appropriate	District	Office	as per Comn	nission Rule	1106)	
il Company			. O. 1	Box 1858,	Roswell,	New Mexico	
Well	No. Uni	t Letter H	Section 23	Township	268	Range 37E	
	auth Taa	none On		County	Tes		
11.11.11				te block)	250		
Casing	Test and Ce	ement Job	Ţ	Other (Ex	(plain):		
Remedi:	al Work			Tempo	orarily Ab	andoned	
ure and quantity of ma	aterials used	l, and resu	lts obtai	ned.			
	A		. Jim. Well .	.055 5 5/4-35	en e		
FILL IN BELOW				EPORTS ON	ILY		
	PBTD			Producing	Interval	Completion Date	
lm · · · · · · · ·		TO:1 Seci-	a Diame	<u> </u>	Oil Strin	ng Denth	
Tubing Depth		Oil Strin	ig Diame	eter	OH Still	ig Deptii	
<u> </u>							
<u> </u>		Produci	ng Form	ation(s)			
	RESULTS	OF WORK	OVER				
Oil Production BPD					GOR Cubic feet/	Gas Well Potentia	
TION COMMISSION		I here	by certi best of	ty that the in my knowleds	itormation give	en above is true and compl	
Approved by			Name Original Signed By				
		Positi		. Lowery	R. A.	LOWERY	
			Dist	rict Exp	loitation	Engineer	
		Compa	iny	•			
	Pool THIS IS A R Casing Remediture and quantity of material status in Tubing Depth Tubing Depth Tubing Depth Tion Commission	Pool South Lee THIS IS A REPORT OF: Casing Test and Company Remedial Work Fure and quantity of materials used abandoned as reported well status in near fure Position FILL IN BELOW FOR REMORIGINA PBTD Tubing Depth RESULTS Oil Production BPD RESULTS Oil Production BPD Gas Production BPD TUDING Gas Production BPD TUDING Gas Production BPD	Pool South Leonard Qu THIS IS A REPORT OF: (Check a Grand Casing Test and Cement Job Grand Quantity of materials used, and result abandoned as reported on Forwell status in near future. Position FILL IN BELOW FOR REMEDIAL WORIGINAL WELL DEBTD Tubing Depth Oil String Production RESULTS OF WORK Oil Production Gas Production MCFPD Tion COMMISSION I here to the	Pool South Leonard Queen THIS IS A REPORT OF: (Check appropriate of the content	Address P. O. Box 1858, Well No. Unit Letter Section Township 23 Pool South Leonard Queen THIS IS A REPORT OF: (Check appropriate block) Casing Test and Cement Job Cother (E) Remedial Work Tempor Tempor County Other (E) Remedial Work Tempor Tempor Company Position Company FILL IN BELOW FOR REMEDIAL WORK REPORTS ON ORIGINAL WELL DATA PBTD Producing Tubing Depth Oil String Diameter Producing Formation(s) RESULTS OF WORKOVER Oil Production BPD Gas Production MCFPD Ware Production BPD Tibereby certify that the into the best of my knowled to the best of my knowled Company Position Name R. A. Lovery Position District Exp	Vell No. Unit Letter Section Township 268	