

X			

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Las Cruces
Lease No. 032510(b)
Unit Dublin

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Clear-out</u>	<u>X</u>
	<u>Sand-oil treatment</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 22, 1963

Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 24

NW 1/4, NW 1/4 Sec. 24 26-S 37-E NM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Leonard Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4991 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Rigged up double drum unit. Pulled 2-1/2" tubing.
2. Ran sand pump, cleaned out open hole from 3433'-57' (T.D.)
3. Sand-oil treated w/20,000 gal. refined oil, 40,000# sand in two stages w/500# crushed moth balls after 10,000 gal.
4. Ran 109 (3358') 2-1/2" J-55 tubing w/31' mud anchor set at 3411'.
5. Swabbed in well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Texas Pacific Coal and Oil Company

Address P. O. Box 1688

Hobbs

New Mexico

By [Signature]

Title Petroleum Engineer