NUMBER OF CO	PIES RECEIVED	·····																
SANTA FE FILE U.S.G.S. LAND OFFICE TRANSPORTER PRORATION OF			ISCELLAN	IEDÛ	REP	ORTS OF		(Rev 3-55										
Name of Company Ad						istrict Office as per Commission Rule 1106) 62 JUL 3 AM 10 28 Address												
	Shell C	P. O. Box 1858, Roswell, New Mexico																
Lease	Scarborou		l No. Unit	Letter F	Section 24	Township	268	Range 37E										
Date Work Pe 5-15-62	rformed	Pool South	Leonard-Qu	een	1	County	Lea											
THIS IS A REPORT OF: (Cbeck appropriate block)																		
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):																		
Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, and results obtained.																		
 Drilled 3439' - 3570'. Ran 15 jts. (484') 4 1/2", 9.5#, J-55 liner and cemented at 3569' v/100 sx. regular neat cement v/4% gel. Top of liner at 3091'. Drilled cement 3144' - 3178', pressured casing to 1000 psi for 15 minutes, OK. Drilled cement 3178' - 3542', pressured casing to 2300 psi for 25 minutes, OK. Ran Otis hookwall packer and Sweet hydraulic holddown immediately above packer to 3487' and set v/8000# vt. Perforated 4 1/2" liner 3502' - 3508' w/2 JSFF. Treated v/250 gallons MCA. Swabbed dry. Treated via 7" casing & 4 1/2" liner w/10,000 gallons lease crude containing 20 - 40 Mesh sand and 1/20# Mark II Adomite/gallon. Ran 115 jts. (3510') 2", J=55; upset (10 jts. 8rd thd, 103 jts. 10V), hung at 3512', Seating Nipple at 3508'. Ran Pump and rods and recovered load. In 24 hours pumped 70 B0 + 8 BM w/12-44" SBM. Gravity 38 deg. AFI. 																		
Witnessed by H. B. Brooks Production					Foreman Shell 011 Company													
	· · · · · · · · · · · · · · · · · · ·	FILL IN BELOW	FOR REME			PORTS ON	ILY		FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY									
D F Elev. 2992' T D 3440' PE				*	Producing Interval Completion D			Completion Date 2-10-50										
Tubing Diam	eter 2"	Tubing Depth	3427'	Oil Stri	ng Diame	ter 7'	Oil String	Depth 3253'										
Perforated In	terval(s)					· •		J~/J	•									
								<u> </u>										
Open Hole In		· · · · · · · · · · · · · · · · · · ·		Produci	ng Forma		· · · · · · · · · · · · · · · · · · ·	<u> </u>										
Open Hole In		3253' - 344 0'			-		Queen	3673										
Open Hole In Test		3253' - 3440' Oil Production BPD	RESULTS OF Gas Produc MCFPI	WORI	OVER Water P		!	Gas Well Pot	ential									
	Date of	Oil Production	RESULTS OF	tion	OVER Water P	ntion(s) Production	Queen GOR	Gas Well Pot MCFPD	ential									
Test Before	Date of Test	Oil Production BPD	RESULTS OF Gas Produc MCFPI	WORN	OVER Water P	ntion(s) Production	Queen GOR Cubic feet/Bt	Gas Well Pot MCFPD	ential									
Test Before Workover After	Date of Test 5=62 6=30=62	Oil Production BPD 3	RESULTS OF Gas Produc MCFPI not measure	work tion	Water P B by certif	Production PD - 8	Queen GOR Cubic feet/Bt not measu 8661 formation given	Gas Well Pot MCFPD										
Test Before Workover After	Date of Test 5-62 6-30-62 OIL CONSERVAT	Oil Production BPD 3 70	RESULTS OF Gas Produc MCFPI not measure 606	work tion	Water F B by certif	Production PD 8 y that the in	Queen GOR Cubic feet/Bt not measu 8661 formation given e. Origina	Gas Well Pot MCFPD ured •										
Test Before Workover After Workover	Date of Test 5=62 6=30=62	Oil Production BPD 3 70 TION COMMISSION	RESULTS OF Gas Produc MCFPI not measure 606	WORN tion ured •3 I here to the	Water P B by certific best of R. Dis	Production PD 8 y that the in my knowledg	Queen GOR Cubic feet/Bt not measu 8661 formation given e. Origina	Gas Well Pot MCFPD wred above is true and c al Signed By LOWERY										