


SCOUT REPORT NEW MEXICO

OIL CONSERVATION COMMISSION



Company Ohio Oil Co.
 Farm Name Mary Wills Well No. 1
 Land Classification _____
 Sec. 35 Twp. 26 Range 37 County Lea
 Feet from Line: 660 N. S. E. 1980 W.
 Elevation _____ Method Rotary
 Contractor Noble Scout _____
 Spudded 9-15-38 Completed _____ Initial Production _____
 Bond Status _____

ACID RECORD

Casing and Cementing Record

Size	Feet	Inches	Sax Cement
<u>12 1/2</u>	<u>214</u>		<u>160</u>
<u>9 5/8</u>	<u>1462</u>		<u>500</u>
<u>4"</u>	<u>2923</u>		<u>50</u>
<u>2</u>	<u>1800</u>		<u>1800</u>

Gals.

Prod.	Date
Prod.	Date

Top Pay

Total Depth

SHOOTING RECORD

No. of Quarts	Shot at	Feet
No. of Quarts	Shot at	Feet

Date		Date	
<u>8-23</u>	<u>Bldg. Road</u>	<u>OCT 25 1938</u>	<u>T.D. 3300 L</u>
<u>8-30</u>			
<u>SEP 7 - 1938</u>	<u>Rd. Road</u>		
<u>SEP 12 1938</u>			
<u>SEP 19 1938</u>		<u>NOV 1 - 1938</u>	<u>T.D. 3300 L</u>
<u>SEP 26 1938</u>	<u>6 1527 H. H. H.</u>		
		<u>NOV 8 - 1938</u>	<u>3300 L - SP. 300 ft. long</u>
<u>OCT 4 1938</u>	<u>2780 H.</u>		
<u>OCT 11 1938</u>	<u>3070 L</u>		
	<u>Cord 3050-63 1/2</u>		
<u>OCT 18 1938</u>			

Abstract

Depth	Formation	Depth	Formation
1210	Anhydrite		
14	X		
45	A		
1381	X + H		
69	A		
1710	X + H		
20	A		
1530	X + G		
1616	X + S + R - J		
98	H		
1710	X + H		
1910	X + Shells		
2043	X + H		
2070	A + G		
2189	X + Shells		
2220	A		
70	X + Shells		
87	X + A		
2313	A		
20	X + Shells		
2390	A + G		
2409	A		
2415	X + A		
20	X + Shells		
50	A		
58	X + Shells		
69	X + D		
72	A + G		
2510			
07	A + G		
46	A + Shells + Y		
85	A		
2724	X + A Shells		