



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces

Lease No. 954040

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT..... XX
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 25, 1964

Well No. 1 is located 660 ft. from SW line and 660 ft. from E line of sec. 17

SE/4, SW/4 of Sec 17
(1/4 Sec. and Sec. No.)

T-23-S
(Twp.)

R-36-S
(Range)

RMZ1
(Meridian)

Mosament Draw Division
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3317 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

WELL FLEECED AND ABANDONED

Spotted 25 shs. @ 8300'-8100'
Recovered 7010' of 5 1/2" Casing
Spotted 25 shs. @ 7030'-6830'
Spotted 25 shs. @ 3939'-3839'
Recovered 1902' of 4-5/8" Casing
Spotted 25 shs. @ 1520-1480'
Spotted 25 shs. @ 450- 350'
Placed 25 shs. on surface (0'-50')
Cemented marker in collar.

COPIED

1006

J. E. JOHNSON
AG. OF PROJ. ENGINEER

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. E. INGERTT, INCORPORATED

Address P O BOX 1005

MIDLAND, TEXAS 79701

By _____

Title Agent