

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240  
**DISTRICT II**  
P.O. Box Drawer DD, Artesia, NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|  |  |
|--|--|
| WELL API NO.                                       | 30 025 12365   |
| 5. Indicate Type of Lease                          | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil / Gas Lease No.                       | B-9312   |
| 7. Lease Name or Unit Agreement Name               | MEXICO -L-   |
| 8. Well No.  | 1  |
| 9. Pool Name or Wildcat                            | DOLLARHIDE FUSSELMAN   |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3156' GL   |

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

|  |   |
|--|---|
| 1. Type of Well:                                   | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   |
| 2. Name of Operator                                | TEXACO EXPLORATION & PRODUCTION INC.  |
| 3. Address of Operator                             | P.O. BOX 730, HOBBS, NM 88240   |
| 4. Well Location                                   | Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line<br>Section <u>5</u> Township <u>25S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3156' GL  |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ REQUEST TA STATUS

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/6/95: MIRU.

4/7/95: TOH with production equipment. TIH with casing scraper and cleaned out to 1266'.

4/10/95: Set CIBP @ 8466' and capped with 35' cement.

4/11/95: Circulated inhibitor fluid. Pressure tested casing and plug to 300 psi for 30 minutes <held>.

Texaco respectfully requests permission to re-classify the subject well to TA status.

Justification: The subject well is located within the West Dollarhide Drinkard Unit. Texaco would like to hold the wellbore in TA status in the event that it is needed for a replacement well in the future.

The original pressure chart is attached to this form. A copy can be found on the reverse side of this form.

This Approval of Temporary  
Abandonment Expires 5-1-2000


I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE [Signature] TITLE Engineering Assistant DATE 5/9/95  
TYPE OR PRINT NAME Darrell J. Carriger Telephone No. 397-0426

(This space for State Use)  
**ORIGINAL SIGNED BY JERRY SEXTON**  
**DISTRICT I SUPERVISOR**

APPROVED BY [Signature] TITLE [Signature] DATE MAY 11 1995

CONDITIONS OF APPROVAL, IF ANY:





TEXACO  
MEXICO "L" # 1  
C.I.B.A. @ 8466 w/ 35' CNT  
4-11-95

Lennie Dickson TEXACO

Rapport Carter per  
Chaparral

1000  
Carter