



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Hobbs, N.M.  
Lease No. NM 0569  
Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

El Paso Ginsberg \_\_\_\_\_ September 19, \_\_\_\_\_, 19 69

Well No. 1 is located 1980 ft. from N line and 560 ft. from E line of sec. 7

NW 7 25 38E  
( $\frac{1}{4}$  Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Justis Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3160 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Subject well re-entered 7-14-69 to test Penn Detritol. Cleaned out to 8606.  
Logged to be plugged & abandoned w/ 25 sx @ 8500, 25 sx @ 6950, 25 sx @ 5150,  
25 sx @ 2650, 10 sx @ Surface

*Not to be filled in - and return plug*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lohmann Oilwell Service, Inc.

Address 202 W. Broadway Place

Hobbs, New Mexico 88240

By [Signature]  
Title President

