

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW M O OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

# MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company	Bob Dean, Ltd.			Address			W. Pickett, 901 Midland Savings Bldg. Midland, Texas		
Lease	Reese Cleveland	Well No.	1	Unit Letter	M	Section	9	Township	25-S
								Range	38-E
Date Work Performed	9-18-62		Pool	Undesignated			County	Lea	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):  
☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

TD 3910'. 20-sack cement plug at 3800'; 20 sx at 2700'; 20 sx at 1500'; 20 sx in bottom of 8-5/8" surface casing; 10 sx in top of 8-5/8" surface casing; 4' steel marker in top. Operator will level pits and clean up location. (Heavy mud between all cement plugs). 20-sack plug in bottom of surface casing is at 310'.

Witnessed by	Robert A. Dean	Position	Operator	Company	Bob Dean, Ltd.
--------------	----------------	----------	----------	---------	----------------


## FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

### ORIGINAL WELL DATA

D F Elev.	TD	PBTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

### RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by	Leslie A. Clements	Name	
Title		Position	Agent
Date		Company	Bob Dean, Ltd.