

NO. COPIES RECEIVED	
DISTRIBUTION	
DATE	
U.S. S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL AND GAS COMMISSION

Form O-103
Supersedes Old
O-102 and O-103
Effective 1-1-65

Indicate Type of Lease	Rate <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
State Oil & Gas Lease No.	
B-9521	

SUNDY NOTICES AND REPORTS ON WELL
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL A WELL OR TO RE-DRILL A WELL IN A PERMIT RESERVOIR.
USE "APPLICATION FOR PERMIT" FORM FOR SUCH PURPOSES.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator	3. Name of Leaseholder
	Skelly Oil Company	Hobbs "A"
4. Address of Operator	5. Well No.	
P. O. Box 1351, Midland, Texas 79701	4	
6. Location of Well	7. Field and Pool, or Acreage	
UNIT LETTER F 1980 North 1650	Langlie Mattix	
THE West LINE, SECTION 30 TOWNSHIP 25S RANGE 38E N.M.P.M.		
8. Depth of Well	9. County	
3079' DF	Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	RE-DRILLING <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	RE-DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGING DEPTH <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state the nature and extent of the work) SEE RULE 1103. 18. Indicate dates, including start and date of starting any proposed work.

- 1) Moved in pulling unit 6-11-73. Pulled rods and tubing.
- 2) Set 5-1/2" bridge plug at 3000'.
- 3) Circulated hole with 10.2# mud.
- 4) Spotted 42' cement plug on top of bridge plug 2958-3000'.
- 5) Shot off and salvaged 5-1/2" OD casing at 2280'.
- 6) Spotted 35 sack cement plug across 5-1/2" OD casing cut off point 2214-2330'.
- 7) Spotted 35 sack cement plug across 8-5/8" OD casing shoe 964-1080'.
- 8) Spotted 10 sack cement plug from surface to 10'.
- 9) Set dry hole marker.

The 8-5/8" OD 32# casing set at 1030, and 5-1/2" OD 15.5# casing from 2280-3330' were left in the open hole.

All intervals not cemented were filled with 10.2# mud.
Well plugged and abandoned 6-14-73.

19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) **D. R. Crow** **D. R. Crow** Lead Clerk DATE **June 27, 1973**

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: