- X. Gamma Ray-Neutron log attached.
- XI. No water wells were observed on a Topographics Surveys Map of the area.
- XII. After examining available geologic and engineering data, there is no evidence of open faults or any hydrologic connection between the disposal zone and any underground source of drinking water.

## XII. Proof of Notice

- A. Certified letters sent to the surface owner and offset operators (Attachment  ${\tt E}$ )
- B. Copy of legal advertisement (Attachment F).