Form 9-331 a (Feb. 1951)							

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	New	exico			
Lease No.	0559				
Unit	¥	<del>-</del>			

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTE	OF INTENTION TO DRILL SUBSEQUENT REPORT OF WATER SHUT-OFF.				
NOTICE OF INTE	NTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.			
NOTICE OF INTE	NTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.			
NOTICE OF INTE	NTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
NOTICE OF INTE	NTION TO SHOOT OR ACIDIZE				
NOTICE OF INTE	NTION TO PULL OR ALTER CASING				
NOTICE OF INTE	NTION TO ABANDON WELL				
	(INDICATE ABOVE BY CHECK MARK N	ATURE OF REPORT, NOTICE, OR C	THER DATA)		
		Rossell, G.W.	December 7	., 19. 🔁	
EDERAL GIV		.w	( <b>***</b>		
Well No.	is located 660 ft. from	line and fr	t. from $\left egin{array}{c}lackbox{V}\end{matrix} ight $ line of sec	. 31	
atsat Sec.	/4	Range) (Meridia			
	Too Too		le# Sexico		
Justis Dii	ield) (County or	Subdivisior.)	(State or Territory)		
12/1/61	TO 5929. La" liner set 0 50 Pecovered selt water w/ trace Fan tubing to 5920'. Set 25 5522-5018. After setting of	ee of oll. Fax cament olum 5	920 - 5 <b>725 and 2</b> 0	ex plug	
12/4/61	Tested casing a/3000%. Hels 1010-02; 5272-60; 5179-72: Perf w/one bullet of the followith tie-in shoe on bottom. Treated down 49" with 21,42	5157-43 & 5130-22.  ceing places: 321   3273, 3281, 325   Tled into 45" 11:   cals lease conde	#/jets 2 noies p 4, 3213, 3221, 32 7 & 3289. Fan 4 or 79311.	er 1001. 35, 3236; " tubing 700# adomite	
12/7/61	After recovering load oil,	tested 4% this oil /ac tubing.	in 4 hrs. Prop	TO KITI ACT	
I understand	that this plan of work must receive approval in	writing by the Geological Surve	y nerore operations may be cor	macilea.	
Company Li	DNARD OIL CO PARY				
Address	P.O. BOX 400		GINAL SIGNED A	/	
	ROSVELL, MEN MEXICO		/LER MIX 11/1AL MANAGER	<b>-</b>	
		Title	GENECAL MANAGER		