

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY1. Office New MexicoLease No. NM - 0889

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas 10 - 26, 19 50Well No. 2-Self is located 1980 ft. from N line and 660 ft. from Ex line of sec. 7

N. W. 4 26-S 38-E N M P
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Lea New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3017 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On Oct. 20, 1950 after an elapsed time of 72 hours from which time 603' of 13 3/8" had been cemented: Hole was bailed dry and tested for 3 - Hours, at which time hole was dry: Plug was drilled, bailed dry and tested for a period of 4 Hours, and found to be dry. As both tests indicated a complete shut off had been obtained, normal drilling was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ralph LoweAddress Box 832Midland, TexasBy W. A. TaylorTitle Agent