


Las Cruces

(SUBMIT IN TRIPLICATE)

Land Office 030139 b

Lease No. 6

Unit



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lynn B-26 June 4, 1963

Well No. 6 is located 660 ft. from ~~section~~ line and 660 ft. from ~~section~~ line of sec. 26
NE/4 NW/4 Sec. 26 23-S 36-E N14W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
MTU Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3384 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded at 7-00 PM, 5-30-63. Ran 323' 7 5/8" OD 24 1/2 casing set at 330' with 200 sacks cement w/4% gel. Plug down at 1:30 PM, 5-31-63. Cement circulated. WOC 24 hours. Tested casing with 1000 PSI for 30 minutes before & after drilling plug. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continent 1 Oil Company

Address Box 68

Dunice, New Mexico

By District Superintendent

USGS-3 14200-2 File