

APPROVED

(SUBMIT IN TRIPLICATE)

SEP 20 1963

UNITED STATES

DEPARTMENT OF THE INTERIOR

ACTING DISTRICT ENGINEER GEOLOGICAL SURVEY

Land Office

Lease No.

Unit

SEP 19 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

G.M. Parksworth "A"

September 16,

19

Well No. 10 is located 1650 ft. from N line and 1663.2 ft. from E line of sec. 18

NE/4 SE/4, Sec. 18,

T-26-S R-37-E

NMPM

Jalmar (1/4 Sec. and Sec. No.)

(Twp.) Lea

(Range)

(Meridian)

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is NYA ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cactus Drilling Company spudded 11" hole at 1-00 PM on 9-14-63. On 9-15-63, 8-5/8" OD 24# J-55 casing was run and set at 362' with 150 ex cement circulated. After 18 hours tested casing with 1000 PSI for 30 minutes. Test OK, reduced hole 7-7/8" at 362' and resumed drilling operations.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Pan American Petroleum Corporation

Company

Post Office Box 68

Address

Hobbs, New Mexico

By

Area Superintendent

Title

