
(SUBMIT IN TRIPLICATE)



UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

			 	·
	it	~ =		
1				
•••				٠.,

Lease No. NH-046420

Land Office

04405-250-08

MAR 1 2 1933

SUNDRY NOTICES AND REPORTS ON WELLS					
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT				
(INDICATE ABOVE BY CHECK MAR					

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Leonard Federal		March 11 , 19 63
Well No. 1 is located	ft. from $\begin{bmatrix} N \\ 1 \end{bmatrix}$ line and $\begin{bmatrix} 660 \\ 1 \end{bmatrix}$	ft from [E] lim (
(½ Sec. and Sec. No.)	26 B 34 E NM	PM .
Vildeat. (Field)	(County or Subdivision) (Meric	dian)
The elevation of the derrick flo	oor above sea level isft.	(State or Territory)
	DETAILS OF T	•

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned 1/14/63 as follows:

34 sacks 6200 - 6300 (Total depth 6900 with 8 5/8 @ 326) 34 macks 5000 - 5100

34 sacks 1050 - 950

625 - 675

300 - 350

10 sacks in top 8 5/8" with regulation marker. 10.5# mud between all plugs.

Location is cleared and levelled and ready for inspection.

	weekerrous
I understand that this plan of work must receive approval in writing by th	• Geological Survey by
Company Nex M. Wilson	our vey before operations may be commenced.
Address c/o Oil Reporte and Gas Services	
Box 763	By It. Lamit
Hobbe, How Hext.so	Title Agent