



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 100-1000

Lease No. 100-10

Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 400 ft. from [N] line and 400 ft. from [E] line of sec. 7
4-1 1/4 Sec. 7 10-1 3-1 10-1
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
400 10-1 10-1
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2274 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled at 10:30 A.M. 7-10-53. Run 511' 7 1/2" casing and set at 353' 7/8" set at 1/2" set. Out circulated. 10-10-53. 511' casing 1/2" set at 10:30 A.M. before and after drilling plug. 10-10-53.

This well was formerly designated 100-10-10.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 60

Unice, New Mexico

Unice, New Mexico

By

Title Assistant Superintendent