

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instruction
verse side)Form approved
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Nov 5 10 19 AM '63	5. LEASE DESIGNATION AND SERIAL NO. 9-331A
2. NAME OF OPERATOR Pan American Petroleum Corporation	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 68 - Hobbs, New Mexico	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FSL X 330' FSL of Sec. 13 (Unit I, NE 1/4 SE 1/4 of Sec. 13)	8. FARM OR LEASE NAME C. N. Jarnes "A"
14. PERMIT NO.	9. WELL NO. 8
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2596' RDB	10. FIELD AND POOL, OR WILDCAT Field
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 13-26-36 NPM
	12. COUNTY OR PARISH, STATE Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENTS ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) ☐		(NOTE: Report results of multiple completion or well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance with Form 9-331a dated July 11, 1963, this well was plugged and abandoned as follows: Spotted 25 sx cement plug across perforations 3080-27', plugged hole, Out and pulled 4 1/2" casing from 2530'. Spotted 25 sx plug in and out of stab. Spotted 25 sx plugs at 2740'; 1290'; and 329'; 10 sx plug at surface with P X A marker. Cleaned and levelled location and restored ground to its natural contour.

18. I hereby certify that the foregoing is true and correct
Original Signed by:

SIGNED V. E. STALEYTITLE Area SuperintendentDATE October 29, 1963

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

OCT 31 1963

J. L. GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

