

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC-030180-(b)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Drilling
2. NAME OF OPERATOR Pan American Petroleum Corporation
3. ADDRESS OF OPERATOR Box 68, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2310' FNL X 1657.9 FWL, Sec. 7 (Unit F, SE/4 NW/4)
14. PERMIT NO.
15. ELEVATIONS (Show whether DT, RT, GR, etc.)

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME C.M. FARNSWORTH "B"
9. WELL NO. 7
10. FIELD AND POOL, OR WILDCAT JALMAT (OIL)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7-26-37 NMPM
12. COUNTY OR PARISH LEA 13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

ABANDON OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spudding
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. INDICATE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

Cactus Oreg Co., spudded 11" hole at 1:15 PM on 8-2-65. At 9: PM, 8 7/8" OD 24# J-55 casing was set at 354' and cemented w/ 200 SX. Incon. Cement circulated. After N.O.C 18 hours tested casing w/ 1000 psi for 30 minutes. Test O.K.

Reduced hole to 7 7/8" at 354' and resumed drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED V. A. STALEY

TITLE Area Supt


DATE 8-4-65

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side



(0+7)
0+4- USGS
1- JWB
1- SWS
1- WY3