

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
LC 030180(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <i>Drilling</i>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR <i>San American Petroleum Corp</i>		8. FARM OR LEASE NAME <i>C.M. FARNSWORTH "B"</i>	
3. ADDRESS OF OPERATOR <i>Box 68 Hobbs N.M. 88240</i>		9. WELL NO. <i>8</i>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>990' FNL X 1656.7' FWL, Sec. 7 (UNIT C, NE/4 NW/4)</i>		10. FIELD AND POOL, OR WILDCAT <i>JALMA - OIL</i>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>7-26-37 NMPM</i>	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH <i>LEA</i>	
		13. STATE <i>NM</i>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

*Cactus Drilling Co. spudded 11" hole at 11:45 AM on 9/27/65. At 7:30 PM 8 5/8" OD 24" J-55 casing was set at 349' w/ 200 sy. Inccy. Cement circulated. After N.O.C 18 hours tested casing w/ 1000 psi for 30 minutes. Test O.K. Reduced hole to 7 7/8" at 349' and resumed drilling operations.*

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed by  
*V. E. STALEY*

TITLE

*Area Supt*

DATE

*9-29-65*

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

\*See Instructions on Reverse Side

OCT 4 1965

J. L. GORDON  
ACTING DISTRICT ENGINEER

⑦  
04-USGS  
1-JWB  
1-5030  
1-4/5