

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANITARY		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-5366	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Doyle Hartman		8. Farm or Lease Name Spear State	
3. Address of Operator 312 Midland National Bank Bldg.		9. Well No. 1	
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>26S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Undesignated	
15. Elevation (Show whether DF, RT, GR, etc.) 3013.3 G.L.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Recomplete in Yates zone</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/11/75 Perforated Queen-Penrose interval with 17 shots at 3449, 54.5, 64, 65, 66, 3503, 05, 21, 25, 33, 37, 47, 49, 62, 64, 66, and 69.

3/12/75 Acidized with 1350 gal 15% HCL and fraced with 40,000 gal and 45,000# sand.

3/13/75 Tested sulfur water with no show of oil from treated interval.

3/14/75 After receiving verbal approval from Joe Ramey, set C.I.B.P. at 3010 with 38' of cement placed on top. Perforated Yates at 2931, 2930, 2918, 2920, 29.22, 2788, 2780, 2739, 2734, 2707, 2699, 2671, and 2661 with total of 15 holes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Doyle Hartman TITLE Operator-Part Owner DATE March 17, 1975

APPROVED BY John W. Runyan TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: