Fig.				
,5,0 ₂ a ₂				Fee X
CAND HE I				The Low Bus Lease No.
	egogia en la segonia en la Esta en la segonia en la s			A process of time
	Water Well			e Sur Francisco
				Jal Water System
Skelly Oil Compar	ıy			
P. O. Box 1351, Midland, Texas 79701				3 . <u> </u>
Majarana M	1313	South	1377	
West	Z,	24S	W.E.	
	Unkn ow n		Lea	
				and the state of t

Production had declined to 4 bbls. per minute. The following work was done to restore it to production:

Clear out

- 1) Moved in and rigged up workover rig. Pulled 5-1/2" tubing and pump.
- 2) Ran bit and cleaned out 3552' 4500'. Recovered silt, sand and iron sulphide particles.
- 3) Reran 5-1/2" tubing and pump and returned well to production status on September 5, 1971, producing 15,840 bbls. water per day from open-hole section 3875' - 4500' of the Capitan Reef formation.

(Signed) D. R. Crow

The state of

No. of the section

DISTE BUT VE

Lead Clerk

Sept. 21, 1971

LINE ABANDONMENT (_ .

it. Santrag are proposed

SEP 23 1971