

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. OIL CONS. COMMISSION
P. O. BOX 1930
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1124.

5. LEASE DESIGNATION AND SERIAL NO.

LC 030187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. E. LaMunyon

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

San Andres

11. SEC. T. R. M. OR RLK. AND
SURVEY OR AREA

Sec 22-T23S-R37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ SWD

2. NAME OF OPERATOR

Gulf Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 2180' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3282' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Repair Pressure ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

POH with packer and tubing. Set RBP at 3000', test 500#. Spot 10' sand on RBP. Perf at 940' with (4) 1/2" JH 90° phase. Establish circulation. Set cement retainer at 878'. Pumped 150 sacks Class "C" 4% gel & 50 sacks Class "C" neat. Circulate 50 sacks cement out 5 1/2" & 8-5/8". Squeeze 500#. Drill cement retainer and cement. Circulate hole clean. Test casing 500#. Wash sand off RBP and POH. Pump 1000 gals 15% NE. Disposed 910 barrels in 24 hours. Complete after repairing flow 10-31-82.

RECEIVED

NOV 17 1982

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED R. D. Putte

TITLE Area Engineer

DATE 11-12-82

(This space for Federal or State use)

APPROVED BY WALTER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 14 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side