


Current
Well Condition

After
Plug & Abandonment



McCulloch Oil & Gas Corp.
Monument Draw 6 Well No. 1
Sec. 6, T23S-R38E
Lea County, New Mexico