

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC.
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC 068281 (B)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
Continental Oil Company

8. FARM OR LEASE NAME
Russell 30 Federal

3. ADDRESS OF OPERATOR
Box 460, Hobbs, NM 88240

9. WELL NO.
8

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT
N. Mason-Ramsay

2310' FSL & 2310' FWL OF SEC 30

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30 T. 26S. R. 32E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3135' GR

12. COUNTY OR PARISH 13. STATE
Lea N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) **Plug Back to Ramsay Formation**
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug Back From the Wildcat-Cherry Canyon (Non-Productive) as Follows:

Set Baker Retainer AT 4442' IN 7" CSG & CMT w/375SX Class "C" CMT and 2% CACL. Perf w/2 JSPF 4254-58' and 4262-66'. Inst. 2 3/8" Tbg set AT 4304'. Installed Test Pumping Unit and Testing AT the Rate of 5 Bbls o. l and 89 Bbls Water IN 24 Hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED **Bill Penfrow** TITLE **adm supervisor** DATE **10-22-76**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
OCT 27 1976
GEOLOGICAL SURVEY
NEW MEXICO

*See Instructions on Reverse Side

USGS (5), File

RECEIVED

2 1973

OIL
NEW COMM.
HUBBS, N. M.