Form 9–331 Dec. 1973	Form Approved.
UNITED ST, _S	Budget Bureau No. 42-R1424
UNITED ST. S DEPARTMENT OF THE INTERIOR OF TO	O5. TEASE
DEFARTMENT OF THE INTERIOR COPY	LC 030467 (B)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	NMFU
reservoir, use runni 3-001-c for such proposals.)	8. FARM OR LEASE NAME 5 8 5 8
1. oil gas	VAUGHN B-1
well well other	9. WELL NO. 📆 💆 ğ 💆 g
2. NAME OF OPERATOR	<u> </u>
CONTINENTAL OIL COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR A A CONTRACTOR A A CONTRACTOR A CO	LANGLIE MATTIX QUOON
Box 460, HOBBS, N.M. 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	C AREA THE STATE OF THE STATE O
below.) AT SURFACE: 1980'FNL +660'F5L	Sec. 1, T-245, R. 36E
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Les NM.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 800 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
REPORT, OR OTHER DATA	
, ·	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3322 GR
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	ုက္ ကု ကို ကိုနီမာမိုး မြို့မရှိနှံနှံ
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
CHANGE ZONES	그는 그 일이 하면서와 그걸고 힘살아 꽃이다.
ABANDON* / S. A. T.	그 그는 그를 가 확실실을 가 물 등록수를 갖는 것
(other) Sof 878 Surface (59.	그 그는 물 이 활동을 하는 활동을 한 사람들이다.
	<u> </u>
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di</li> </ol>	e all pertinent details, and give pertinent dates,
measured and true vertical depths for all markers and zones pertinen	t to this work.)* 高麗金麗 吳 紫海海
- 11 / - 4	
5 pudded 9-6-77 and Drille	1 124" Holo TO 1191"
Ran 85%, 24 H, K-55 CS 9 50 f A 5x C/155 "C" CMT and 2/6 C AT 3:00 AM 9-7-77. W.O. CS9 TO 800 PS/. Hold OK. Di	T 1101 1 A
Man 82 24 H, 1-55 CS 7 307 M	11186 CM/D W/625
The ches "" CMT and 2/0	ACLZ, Plug Down
37 21 10 9 7 77 110	1841 - Tall
A7 3:00 AM 1-1-11. WID.	-, 10,777,3, 145766
COG TO 800 PSI. Hold Ok. Di	Id Ahead With 77%
	18
Hole.	
	그 그는 그는 한 회장 총일 그는 것이 한 것이 없다.
	기원회사의 일 개 회실식품
	회장 사람이 가는 기를 가는 것이 되었다.
Subsurface Safety Valve: Manu. and Type	နှစ်တွင် မြို့သည်။ မြို့သည်။ နောက်သည်။ မြို့သည်။ မြို့သည်။
•••	Set @Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED THOU OF THE THE ADMIN SU	W 9-9-77

(This space for Federal or State office use)

\_ DATE \_

\_\_ TITLE

4565-5, NMFU Partners (4), File

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

J. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO