

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☐ gas well ☐ other
2. NAME OF OPERATOR  
Getty Oil Company
3. ADDRESS OF OPERATOR  
P. O. Box 730, Hobbs, New Mexico 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: UNIT LTR N, 660' FSL & 1980' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO:   |                          | SUBSEQUENT REPORT OF: |                          |
|----------------------------|--------------------------|-----------------------|--------------------------|
| TEST WATER SHUT-OFF        | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| FRACTURE TREAT             | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE           | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| REPAIR WELL                | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| PULL OR ALTER CASING       | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| MULTIPLE COMPLETE          | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| CHANGE ZONES               | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| ABANDON*                   | <input type="checkbox"/> |                       | <input type="checkbox"/> |
| (other) Casing Connections |                          |                       |                          |

5. LEASE  
LC-057420
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
-
7. UNIT AGREEMENT NAME  
Myers Langlie Mattix Unit
8. FARM OR LEASE NAME  
-
9. WELL NO.  
48
10. FIELD OR WILDCAT NAME  
Langlie Mattix
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 28, T-23-S, R-37-E
12. COUNTY OR PARISH  
Lea
13. STATE  
NM
14. API NO.
15. ELEVATIONS: (SHOW DF, KDB, AND WD)  
3303 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Riser on 8 5/8" OD and 5 1/2" OD Casing brought to surface.

Inspected by M. G. Crossland on September 1, 1978.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett TITLE Area Supt. DATE 9-19-78

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

