Casing Report El Paso Plant No. 1 Lea County, New Mexico

1 Howco Guide Shoe	1.00'
1 Joint 5½" Casing	16.58'
1 Howco Float Collar	1.80'
82 Joints $5\frac{1}{2}$ " Casing	3,280.62
Total	3,300.00'

Plugged back Total Depth is 3,280.62'

Cemented with 455 sx.Halliburton Lite with $\frac{1}{4}$ lb. F.C. per sack and 250 sx. of 50-50 Pozmix with 5 lbs. salt per sack and $\frac{1}{4}$ lb. F.C. per sack. Circulated 45 sx. to pit. Bumped plug w/800 PSI. Released and held O.K. Job completed 6:00 P.M. 10-3-79. Completion operations will commence when pipeline ROW is obtained by Gathering Company.