

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐2. NAME OF OPERATOR
Getty Oil Company3. ADDRESS OF OPERATOR
P.O. Box 730, Hobbs, NM

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit Ltr F, Sec. 1,

AT TOP PROD. INTERVAL: T26S, R37E

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐

(other) Commence drilling operation

SUBSEQUENT REPORT OF:

RECEIVED
DEC 12 1980
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/5/80 Kenai Drilling Company spudded 15" hole at 12:00 A.M.

12/8/80 Drilled 15" hole to 850'. Ran 21 jts. (837') of 11 3/4" OD H-40 42 & 47# Casing and set at 850' Halliburton cemented w/500 sxs. Class "C" cement w/6% Gel & Flocele and 2% CaCl. Total cement - 700 sxs. Circulated 125 sxs.

12/9/80 Waited on cement 18 hours. Pressured up to 1200# on casing for 30 minutes. OK.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Dale R. Crockett

TITLE Area Supt.

DATE

12/10/80

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER

TITLE

DATE

DEC 15 1980

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side