

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 13430	
2. NAME OF OPERATOR BTA OIL PRODUCERS		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 104 South Pecos Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FEL & 1980' FSL		8. FARM OR LEASE NAME Yea 21, 7406 JV-S	
14. PERMIT NO.		9. WELL NO. 7	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2923' GR		10. FIELD AND POOL, OR WILDCAT Comanche Stateline Tansill Yates	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, Twp 26-S. Rge 36-E	
		12. COUNTY OR PARISH Lea	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

Spud & Casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/9/80 Spudded 12:15 PM, Drlg 12-1/4" hole.

12/11/80 Cmtd 8-5/8" 23# csg @ 1397' w/1300 sx cmt., Cmt circ., WOC.

12/12/80 Csg pressure tested OK. Drlg. 7-7/8" hole.

12/19/80 Cmtd 5-1/2" 14# csg @ 3525' w/250 sx cmt., TOC. 2032'. WOC.

12/20/80 Pressure tested csg @ 2500 psi. Held OK. Prep to complete.

18. I hereby certify that the foregoing is true and correct

SIGNED

BOB K. NEWLAND

TITLE

Regulatory Administrator

DATE

1/6/81

(This space for Federal or State office use)

APPROVED BY

ACCEPTED FOR RECORD
PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
Instructions on Reverse Side