

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR  
CONOCO INC.
3. ADDRESS OF OPERATOR  
P. O. Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 1980' FEL  
AT TOP PROD. INTERVAL: —  
AT TOTAL DEPTH: —
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE  
LC-030467(4)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
NMFU
8. FARM OR LEASE NAME  
Vaughn B-1
9. WELL NO.  
9
10. FIELD OR WILDCAT NAME  
Anglie Mattix Seven Rivers Queen
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 1, T-24S, R-36E
12. COUNTY OR PARISH  
Lea
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- |                      |                          |
|----------------------|--------------------------|
| TEST WATER SHUT-OFF  | <input type="checkbox"/> |
| FRACTURE TREAT       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE     | <input type="checkbox"/> |
| REPAIR WELL          | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> |
| MULTIPLE COMPLETE    | <input type="checkbox"/> |
| CHANGE ZONES         | <input type="checkbox"/> |
| ABANDON*             | <input type="checkbox"/> |

- |  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |

(other)  $\text{spnd}$ , set surface csq.

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

**JUL 23 1981**

U.S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MIRU. Spud on 7/11/81. Ran 85/8", 24#, K-55, csg set at 1204'.  
Cmtd w/ 385 sx. Class C, tailed by 200 sx. Class C. Circulate 100 sx.  
to surface.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Wm A. Rutherford TITLE Administrative Supervisor DATE July 21, 1981

ACCEPTED FOR RECORD  
ROGER A. CHAPMAN (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

JUL 27 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side