

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR ARCO Oil & Gas Company
Division of Atlantic Richfield Company
3. ADDRESS OF OPERATOR
P. O. Box 1710, Hobbs, New Mexico 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FEL & 660' FSL (Unit "0")
AT TOP PROD. INTERVAL: As Above
AT TOTAL DEPTH: As Above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED
JUL 9 1981
U.S. GEOLOGICAL SURVEY
HOBBS, N.M.

Spud, run 8-5/8" surf csg & cmt

5. LEASE
LC-032726
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Duthie Andrews Fed
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Langlie Mattix 7R Qn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
18-23S-37E
12. COUNTY OR PARISH
Lea
13. STATE
NM
14. API NO.
30-025-27446
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3331.8' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up on 6/19/81, set 30' of 14" conductor pipe. Cmt'd w/4 yds Redi-mix. Spudded 12 1/4" hole @ 4:30 PM, 6/20/81. Finished drlg 12 1/4" hole to 1165' 6/23/81. RIH w/ 8-5/8" OD 24# K-55 csg, set @ 1165'. Cmt'd w/600 sx Cl "C" cont'g 4% gel, 5# Gilsonite/sk, 1/4# Flocele followed by 250 sx Cl "C" cmt cont'g 2% CaCl₂. Circ 300 sx cmt to surface. PD @ 11:30 AM 6/24/81. WOC 24 hrs. Press tested csg to 1000# for 30 mins, OK. Drill out cmt to 1155' (left 10' in shoe). Displ w/inhibited fluid. ND BOP & NU wellhead with valve. Released rig. Drilling operations temporarily suspended on 6/27/81.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED George J. Schmidt TITLE Dist. Drlg. Supt. DATE 6/29/81

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD (This space for Federal or State office use)
ROGER A. CHAPMAN

JUL 7 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
See Instructions on Reverse Side