

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other inst
verse side)LICATE
3 ON reForm approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM - 28052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

JUN 29 1981

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

John Yuronka

U.S. GEOLOGICAL SURVEY Donna Federal

3. ADDRESS OF OPERATOR

HOBBS, NEW MEXICO

9. WELL NO.

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990' FSL and 330' FEL of Sec. 22

10. FIELD AND POOL, OR WILDCAT

Undesg. Langlie Mattix

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T24S, R36E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3352' DF

12. COUNTY OR PARISH 13. STATE

Lea

N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 10:30 PM on June 19, 1981.

Drilled 12-1/4" hole. TD 445'. Ran 11 joints - 427' - of 8-5/8" 23# J-55 S.T.C. casing and set at 443'. Cemented with 350 sxs. Class "C" Cement with 2% Calcium Chloride. Circulated 100 sxs. 41' of cement left in pipe. Plug down at 12:30 PM on 6-20-81. Tested pipe and cement after 18 hours with 800# for 30 minutes and held OK. Drilled out cement.

18. I hereby certify that the foregoing is true and correct

SIGNED

John Yuronka

TITLE

Authorized Agent

DATE June 24, 1981

(This space for Federal or State office use)

APPROVED BY

ROGER A. CHAPMAN

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 6 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side