

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

P. O. BOX 1980

HOBBS, NEW MEXICO. 88240

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 7 below.)

AT SURFACE: 1980' FNL & 660' FEL

AT TOP PROD. INTERVAL: ✓

AT TOTAL DEPTH: 1

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON *

(other) Complete

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If work is intermittently drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the work.)

CO to 4568'. Perf w/255PF at 4374', 76', 82', 85', 88', 92',
96', 98', & 4401'. Total 18 holes. Break down ports w/20lbs lead-
in TFW and 6466lbs 15% HCL-NH₄ Sol per @ 4374'. Sand oil
frac Ramsey Sand (4374'-4401') w/1000 gelled oil pad. 3866lbs
gelled oil w/26,250# 12/60 sd & 3100# 8/16 sd. Rel pkr.
Ran production equipment. Tested 1-24-58; 6560, 45 MCF & 1053W.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

(ORIG. SGD.) DAVID R. GLASS

APPROVED B
CONDITIONS

OF APPROVAL: **JAN 28 1983**

MINERALS MANAGEMENT SERVICE
ROSWell, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

JAN 28 1983

**OIL & GAS
MINERALS MGMT. SERVICE**

