DEPARIMENT OF THE INTERIOR AND AND A	5. LEASE LC-050107 (b)	
UNITED STATES DEPARTMENT OF THE INTERIOR HALL GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEF OR TRIBE NAME	
SUNDRY NOTICES AND REPOF       ON WELLS         (Do not use this form for proposals to drill or to deeper reservoir. Use Form 9-331-C for such proposals.)       Image: Construction of the proposals.)         1. oil well XI well other       other         2. NAME OF OPERATOR Merathon 0.11 Company       MEXICO         3. ADDRESS OF OPERATOR P. O. Box 2409 Hobbs, NM 88240       MEXICO         4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)       AT SURFACE: 330' FNL & 330' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:         16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA       SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF         FRACTURE TREAT       Image: Constant of the proposal of the proproposal of the proposal of the proposal of	<ul> <li>75UNIT AGREEFMENT NAME</li> <li>75UNIT AGREEFMENT NAME</li> <li>76ARM OR LEASE NAME</li> <li>76UILS Federal.</li> <li>9. WELL NO. <ol> <li>1</li> </ol> </li> <li>10. FIELD OR WILDCAT NAME Rhodes, Yates</li> </ul> <li>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <ul> <li>Sec. 34, T26S, R37E</li> <li>12. COUNTY OF PARISH</li> <li>13. STATE</li> <li>14. API NO.</li> </ul> </li> <li>15. ELEVATIONS (SHOW DF, KDF AND WD) <ul> <li>2970 GR, 2982 KB</li> </ul> </li> <li>(NOTE: Report results of multiple completion or zone change on Form 9-330.)</li>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On January 1, 1984 a RBP was set at 3320' above the lower Yates perforations (3334 - 67). The upper Yates was perforated from 3221 - 3293 with 1 JSPF selectively (25 holes total). These perfs were then treated with 1000 gallons of 15% acid. Then they were fraced with 30,000 gallons of 50-50 CO<sub>2</sub> with 54,000# of 20/40 and 12/20 sand. This zone is presently being swab tested.

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18. Thereby certify that the foregoing is true and correct SIGNED TITLE Production EngineerDATE	1-20-84	
ACCLETED TORE RECEIVER (This space for Federal or State office use)		
CONDITIONS OF APPROVALY IF 1 0 1984	*	
alshed, NEW MEXICO . See Instru. tions on Reverse Side		

MAY 1 4 1984 HOBBES