STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-73
F1LE U.S.G.S.	Sa. Indicate Type of Lease
DPERATOR DEFICE	State Fee X
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FOR POPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAB X OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
HCW Exploration, Inc. 3. Address of Operator	George Etz 9. Weil No.
P.O. Box 10585 Midland, Texas 79702	6
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM	10. Field and Pool, or Wildcat
UNIT LETTER	Jalmat (Gas)
THE East LINE, SECTION 27 TOWNSHIP 23-S RANGE 36-E NMPP	- (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
1 15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3369.3' GR	Lea ())))))
Check Appropriate Box To Indicate Nature of Notice, Report or O NOTICE OF INTENTION TO:	ther Data IT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMPLETION OTHER	ALTERING CASING
Rigged up mast pole truck and wireline truck on 2/18/86. Ran Dual Spaced Neutron log with GR & CCL from 3543' WL PBTD to 2000'. Rigged down loggers. Moved in and rigged up pulling unit on 2/24/86. Cut off 4½" casing and welded on 4½" SOW X 7 1/16" 3000 psi WP wellhead. Install 7 1/16" 3000 psi BOPs. Ran 3 7/8" bit and 2 3/8" tubing inside 4½" casing. Tagged PBTD at 3547' by tubing measurement. Spotted 15 bbls 7½% MSR 100 acid. Pulled tubing & bit. Perforated Yates formation with 3 1/8" select fire casing gun with 1 JSPF as follows: 3164, 66,68,70,72,74,76,78,80,82,84,86,98,3200,02,04,06,08,10,12,14,16,36,38,40,42,44,46,48,50,52, 54,56,61,66,68,70,75,77,79,86,88,90,3304,06,08,18,54,56,58,64,66,68,77,3429. Total of 55 holes, 0.42" diameter. Ran 2 3/8" notched collar, 1 joint 2 3/8" tubing, 2 3/8" SN, and 95 joints 2 3/8" tubing to 3140'. Removed BOPs and installed tubing head. Acidized Yates perforations down 2 3/8" tubing with total of 5500 gals. 7½" MSR 100 acid with 550 scf/bbl N ₂ plus 110 ball sealers. Did not ball out. Flowed and swabbed back load water for 1½ days. Swabbed dry. Frac treated Yates perforations down 2 3/8" tubing and 2 3/8" X 4½" annulus with 40,000 gals. YF3PSD with 550 scf/bbl N ₂ plus 85,000# 20/40 sand and 50,000# 10/20 sand. Flowed back load water. Started making natural gas and oil after flowing well 4 hours to reserve pit. Switched flowline to frac tank and rigged up rental two phase separator. Flowed well through separator putting load water and oil into frac tank and venting gas to atmosphere. Gas was measured using 2" orifice well tester and oil and load water was measured by gauging frac tank and using color cut on gauge line.	
SIGNED Duglas/Steve A. Douglas TITLE Vice President Operations	
CONDITIONS OPIL ANVI	MAR 5 - 1986