

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC034711
2. NAME OF OPERATOR Arch Petroleum Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 10 Desta Dr., Suite 420 East, Midland, Texas 79705		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit L, 2310 FSL & 660 FWL, Section 35, T23S, R37E		8. FARM OR LEASE NAME Baylus Cade Federal
14. PERMIT NO. 9-29-89		9. WELL NO. 4
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3246.2 GR		10. FIELD AND POOL, OR WILDCAT Teague Devonian
		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec 35, T23S, R37E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Install Pumping Equipment

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-08-91 Pulled packer. Ran production tubing and rods as follows:

1 Jt mud anchor
4' perforated sub
seating nipple at 7467
231 jts 2 3/8" 4.7# J-55 tbg
1" x 6' gas anchor
2" x 1.25" x 18' pump
18 - 7/8", 198 - 3/4", 82 - 7/8" rods

2-09-91 Put well on pump using 228 pumping unit and 50 hp motor.

2-10-91 24 hr. well test on pump. 71 BO and 111 BW and 29 MCF.

RECEIVED
MAR 5 11 14 AM '91
CARLOS J. GARCIA
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 3-4-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side