



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Lea County Inspection Section

P.O. Box 1157

Hobbs, NM 88240-1157



IN REPLY REFER TO

## PET CEMENTING REPORT

A. Operator Name ORyx Energy Lease No. \_\_\_\_\_  
S 16 T 24S R 32E Well Name Double X Fed. 16 #01

B. Company doing work Haliburton Called by Bougie Armes  
Date & Time Called 8-11-90 - 2030 Time left office 2100  
Miles to location 55 Time arrived 2230 Time left location 0230  
Was job completed when you left? Yes Time completed? 0200  
Arrived at office 0330 Total hrs out 6 1/2 (office to office)  
Overtime used 6 1/2 comp time 0

C. Complete only those blanks below if the activity was actually witnessed.

Hole depth 4975 Hole size 12 1/4 Casing size & wt. 9 5/8 - 36 #

Time plug was down 0140 Running of casing witnessed? Yes

Shoe depth 4975 Time started pumping cement 0017

Did cement circulate? Yes Amt. of cement run 200 SKS.

Type of cement Class C - 14.5#, 1.39 yield.

If not, was a T/S done? Yes Time ran 1830 By whom John West.

Was the annulus one inched? Yes From what depth? To 400

D. In the following space provide information on what was witnessed and any problems, delays, or other comments relating to the job, such as bad weather, injuries, late arrivals of crew, equipment, etc.

Temperature Survey Ran Showed Top of the Cement AT 530. Ran 1"  
To 400 To complete cementing. Cemented through 1". Circulated  
30 SKS. to the pit.

Inspector Signature Jack Johnson  
Date 8-11 + 8-12-90